

General Environmental Incident Summary

Incident: 9365 **Notice:** 1/9/2020 0845 **Occurred:** 1/9/2020 0845
DEM Incident No: **No Further Action:** ☒
Responsible Party: Farstad Oil Inc
County: Burleigh
Twp Rng Sec Qtr: 138 80 1
Lat Long + Method: 46.80406 -100.73070 Interpolation from map
Location Description: Little Dukes
1144 Bismarck Expressway
Submitted By Info: Roger Pelzer
PO Box 18
Minot ND
Received By Info:
Contact Info:
PO Box 1842
Minot ND
Affected Medium: 09 - other
Near. Occupied Bldg:
Type of Incident: Tank Overflow
Release Contained: Yes
Reported to NRC: Unknown
Contaminant: Gasoline
Volume of Release: 275 gallons
Duration of Release:
Agriculture Related: No
EPA Extremely Hazardous Substance: Unknown
Number of Fatalities:
Number of Injuries:
Cause of Incident:
Driver overfilled a tank
Risk Evaluation:
N/A
Potential Env. Impacts:
Potential of some fuel entered sewer drain
Action Taken/Planned:
Strata Corporation will be cleaning up the spill
Wastes Disposal Location:
Other Agencies Involved:
NDDDES

Updates

Date: 1/9/2020 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report the release of gasoline was not contained. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 1/9/2020 **Status:** Correspondence - More Follow-up Required

Author: DeVries, Taylor

Notes:

Spoke with City of Bismarck to inform them that gasoline has entered the stormwater system. The city of Bismarck will have an inspector out sometime today to assess the spill.

Updated Volume: None at the time of this update

Date: 1/9/2020 **Status:** Inspection - More Follow-up Required

Author: DeVries, Taylor

Notes:

Inspection date: 1/9/2020

Arrived on location at 1400. The location of the spill is where trucks offload gasoline into the underground storage tanks. The gasoline ran down gradient to a storm drain. At time of the inspection, floor dry had been put down and removed. There was not much sign of a spill left. Further follow-up needed with City of Bismarck.

Photos were taken and can be found in the report folder.

Updated Volume: None at the time of this update

Date: 2/27/2020 **Status:** Correspondence - Vegetation Check

Author: DeVries, Taylor

Notes:

Received a few emails from Bismarck Public Works. In review, Farstad Oil had a third party contractor on location with a vac truck and excavator. The inlets were cleaned and contaminated soil was removed from the green space that included some of the fuel filling receptacles. The outfall into the storm water retention pond was cleared of sand and sediment. Further follow-up is needed to assess vegetation regrowth in the summer.

Emails can be found in the incident folder.

Updated Volume: None at the time of this update

Date: 4/30/2020 **Status:** Inspection - No Action Required

Author: Suess, Bill

Notes:

Visited the site on April 29, 2020. No signs of adverse environmental impacts, associated with this spill, were observed. Vegetation looked healthy and consistent with surrounding area. No further action is warranted.

Updated Volume: None at the time of this update

Date: 4/30/2020 **Status:** Correspondence - No Action Required

Author: Suess, Bill

Notes:

Bill Suess sent a No Further Action letter dated April 30, 2020.

Updated Volume: None at the time of this update